


Plat of Survey

Being known as Lot No. 1 of Shady Lawn Subdivision (Plat Vol. 6 Page 112) and a part Lot No. 173 of the Auditor's Plat of Lots to the Village of Hicksville, Defiance County, Ohio.




For... Jeffrey A. Cover & Rodney L. Cover
OR 448 Pg. 2449

I hereby declare that I did perform this survey and that it is correct to the best of my knowledge and belief.

Thomas J. Henry 10-7-22
Thomas J. Henry
Registered Surveyor No. 6787

- A- Capped iron pipe found.
- B- Bar in concrete monument found.
- C- Iron pipes in concrete found.
- D- Iron stake in concrete monument found.
- E- Iron pipe found.
- F- Capped iron pin found, iron pin found .25± north.
- G- Point established.
- H- Chain link fence post.



H-38-001