Plat of Survey

Being a part of the Northwest quarter (1/4) and a part of the Southwest quarter (1/4) of Section 15, Township 5 North, Range 4 East, Tiffin Township, Defiance County, Ohio.

For... Nellie Jean Ziegler, et al

DB 269 Pg. 400



Tiffin River
Normal Low Waterline

ab	S 58°04'07"	W	182.20'
bc	N 26°52'43"	W	88.90'
cd	N 62°36'20"	W	63.83'
de	N 71°17'39"	W	109.73'
ef	N 75°10'29"	W	67.95'
fg	N 77°21'13"	W	330.55'
gh	N 58°16'35"	W	172.23'
hi	N 53°25'13"	W	75.27'
ij	N 47°36'54"	W	66.73'
jk	N 31°10'20"	W	59.76'
kl	N 15°37'44"	W	40.10'
lm	N 10°31'31"	E	44.64'
mn	N 28°47'04"	E	82.97'
no	N 33°18'10"	E	68.08'
op	N 37°44'00"	E	97.93'
pq	N 33°18'03"	E	87.81'
qr	N 35°21'00"	E	78.63'
rs	N 38°20'41"	E	79.61'
st	N 30°13'01"	E	31.91'

Ne Cor Sec. 15

Christy Road

2643.75'

S 1°19'26" E

N 87°32'06" W 3435.58'

E 1/4 Cor. Sec. 15

A– Railroad spike found.
B– Harrow tooth spike found.
C– Iron pin found.
D– Capped iron pin found.
E– Iron pipe found.

0' 280'

STATE OF OHIO
THOMAS HENRY
S-6787
REGISTERED
PROFESSIONAL SURVEYOR

I hereby declare that I did peform this survey and that it is correct to the best of my knowledge and belief.

5-10-21

Thomas J. Henry
Registered Surveyor No. 6787

05-15-36