Plat of Survey

Being a part of the Southwest quarter (1/4) of Section 32, Township 5 North, Range 3 East, Washington Township, Defiance County, Ohio.

For... Daryl L. Caryer, et al

OR 443 Pg. 2842



A– Railroad spike found.
B– Iron pin found.
C– Monument box found.
D– Railroad spike found over monument box.
E– Concrete corner post found.
F– 5/8" iron pin found 1.15 south of corner.
G– 1"x5' iron pipe post found .40 northwest of corner.
H– Mag nail set.
I– Mag nail found.
J– 5/8" capped iron pin set.

0' 600'

I hereby declare that I did perform this survey and that it is correct to the best of my knowledge and belief.

8-29-22

Thomas J. Henry
Registered Surveyor No. 6787

STATE OF OHIO
THOMAS HENRY
S-6787
REGISTERED
PROFESSIONAL SURVEYOR

08-32-18