

RUB, SER
11-06-2007

RICHLAND, ADAMS TOWNSHIPS
#1942 + #3334

INDEPENDENCE ROAD

ADAMS TOWNSHIP
SECTION 33

ADAMS TOWNSHIP
SECTION 34

FLORY ROAD - Capped-iron pipe found
(4" below pavement)
#1942

Monument Box with
Capped IP found
(2 1/2" below pavement)
#3334

R found flush SW Side
T Pole guy pole

R w/ shiner found flush
NW Side power pole

RICHLAND TOWNSHIP
SECTION 4

RICHLAND TOWNSHIP
SECTION 3

TIE-DOWN INDEX

- 1: 46.42' NE
- 2: 29.79' NE
- 3: 32.08' SE
- 4: 49.78' SE
- 5: 46.75' SW
- 6: 29.68' SW
- 7: 21.80' E