

SURVEY PLAT
 PT OF SW 1/4, SE 1/4
 SEC. #15 T5N, R2E
 FARMER TWP, DEFIANCE CO., O.
 CONKEY SURVEY


Vol. 09-15-09

NOTE: Ties Given In County
 Stone Book Are Incorrect For
 SW Corn. SE 1/4. Should Be
 32.00 NW To Hole In W/S CMP
 30.19 NE To Hole In E/S CMP



Scale 1" = 100'

- LEGEND**
- 1) Fd. Bolt
 - 2) Fd. PK
 - 3) Fd. Pipe or Pin
 - 4) Placed PK
 - 5) Placed 5/8" Pin



REF SURVEY
 Eriksen Surveying 1983
 Paul Westoven 1971

Anthony H. Hoeffel
 Anthony H. Hoeffel
 BRYAN ENGINEERING & SURVEYING
 11/15/89
 S-6149
 419-636-2060

*This Survey has been Revised
 By Anthony Hoeffel 9/23/80*