

Plat of Survey

Being a part of the Southeast Quarter ($\frac{1}{4}$) of Section 4, Township 4 North, Range 1 East,
Hicksville Township, Defiance County, Ohio.



NAD 83 (2011)

For... Jacob and Janelle North
E20-0004-0-002-02
Or 441 Page 1281


Kevin & Kallie Countryman
E20-0004-0-004-00
OR 300 Page 2532

Northwest Corner
E 1/2 SE 1/4
Section 4

1306.33' Total
S 88°43'46" E


North Line Southeast 1/4 Section 4
454.66'

East 1/4 Corner
Section 4



Eric & Rebecca Rice
E20-0004-0-002-06
OR 388 Page 750

Drew Wort & Chantel Arnold
E20-0004-0-002-00
OR 219 Page 243



Legend

- A - $\frac{5}{8}$ " Iron Pin Found
- B - Iron Pipe Found
- C - Railroad Spike Found
- D - $\frac{5}{8}$ " Capped Iron Pin Found
- E - $\frac{5}{8}$ " Capped Iron Pin Set
- F - Point Established

0' 100'

I hereby declare that I did perform this survey and that it is correct to the best of my knowledge and belief.

Thomas J. Henry
Registered Surveyor No. 6787

12-04-29