

# Plat of Survey


Being a part of the East half (1/2) of the Northeast quarter (1/4) of Section 7 Township 4 North, Range 4 East, Noble Township, Defiance County, Ohio.

For... Melissa Moninger, et al

OR 437 Pg. 741

Ne Corner Section 7


Buckskin Rd.



- A- Capped iron pipe found.
- B- Iron pin found.
- C- Mag nail set.
- D- 5/8" capped iron pin set.

I hereby declare that i did perform this survey and that it is correct to the best of my knowledge and belief.

Thomas J. Henry  
Registered Surveyor  
No. 6787



East Qtr. Cor.  
Section 7