


# Plat of Survey

Being known as a part of Lot No. 256 and a part of Lot No. 347 of the Auditor's Plat of Lots to the Village of Hicksville, Ohio.

For... Bruce E. & Debra K. Guilford



I hererby certify that I did perform this survey and that it is correct to the best of my knowledge and belief.

Thomas J. Henry  
 Thomas J. Henry  
 Registered Surveyor No. 6787

- A- Iron pin found.
- B- 5/8" capped iron pin set.
- C- 2" PVC pipe filled with concrete.

