Plat of Survey

Being known as Lot No. 13 and a part of Lot No. B of S. & J. Bares Addition; also a part of Lot No. 77 of the Auditor's Plat of Lots; also a part of Lot No. 82 of the Auditor's Plat of Lots; also Lot No. 133 of the Auditor's Plat of Lots; also Lot No. 134 of the Auditor's Plat of Lots; also a portion of Vacated Edgerton Street, located in the Northwest quater (1/4) and in the Southwest quarter (1/4) of Section 21, Village of Hicksville, Township of Hicksville, County of Defiance, Ohio.

For... Crook–Miller Company, Inc., a Division of Baker McMillen Company

Vol. 253 Pg. 211

PN: E06–0011–0064–00 Lot No. 134 Auditor's
E06–0011–0065–00 Pt. Lot 82
E06–0011–0069–00 Pt. Lot 82 Auditor's
E06–0011–0066–00 Lot 133 Auditor's
E06–0011–0067–00 Pt. Lot 77 Auditor's
E06–0012–0051–00 Lot "B" S & J Bares
E06–0012–0059–00 Pt. Lot 13 S & J Bares
E06–0012–0060–00 Pt. Lot 13 S & J Bares



A– Iron pin found.
B– Capped iron pin found.
C– Iron pipe found.
D– 5/8" capped iron pin set.
E– PK nail found set in sidewalk.
F– Point re–establsihed
G– Railroad spike set.

0' 100'

I hereby certify that I did perform this survey and that it is correct to the best of my knowledge and belief.

10-7-19

Thomas J. Henry
Registered Surveyor No. 6787

STATE OF OHIO
THOMAS
HENRY
S-6787
REGISTERED
PROFESSIONAL SURVEYOR

H-043-004
H-01-247